

2015 HLA Road Committee Road Work Pictures


Culvert Repair/Replacement

Heritage Dr @ Old Sandy Beach (middle culvert)





Westminster (large culvert)




Thornton and Greenbriar





Road Reconstruction

Bradford Drive Reconstruction










Spray Patch

Heritage Dr






Kenton



Ditch Work


King Richard Dr





King Richard Dr





King Richard Dr





Hawthorne



Bradford Drive Ditch Work



Wilshire Wood

Maintenance crew is still working on this area. Pictures were taken with work in progress. The road was covered by about 8-10 ft of dirt and brush.



